

LOC/DME I-CFQ
110.35
Chan **40** (Y)

APP CRS
101°

Rwy Idg **4001**
TDZE **928**
Apt Elev **928**

LOC/DME RWY 10

MIDDLETON MUNI/MOREY FLD (C29)

Helicopter visibility reduction below ¾ SM NA. Use Dane County Rgnl-Truax Fld altimeter setting; when not received, use Baraboo altimeter setting and increase all MDAs 60 feet and S-10 Cat C visibility ¼ SM and Circling Cat C visibility ¼ SM. Circling NA to Rwys 1 and 19.

MISSED APPROACH: Climb to 1700 then climbing left turn to 3600 via heading 010° and MSN VORTAC R-282 to IMMES Int/MSN 9.2 DME and hold, continue climb-in-hold to 3600.

AWOS-3 118.675	MADISON APP CON★ 135.45 343.7	UNICOM 123.0 (CTAF) 0
--------------------------	---	--

One Minute Holding Pattern

CERTO I-CFQ [6.5]

2800 ← 281° 101° → 2800

VGSI and descent angles not coincident (VGSI Angle 4.00/TCH 31).

3.06° TCH 31

5.7 NM

I-CFQ [0.8]

1700 3600 IMMES MSN [9.2] HDG 010° MSN R-282

CATEGORY	A	B	C	D
S-10	1580-1	652 (700-1)	1580-1¾ 652 (700-1¾)	NA
CIRCLING	1580-1 652 (700-1)	1640-1 712 (800-1)	1660-2 732 (800-2)	NA

ELEV 928 TDZE 928

101°

10

4001 X 100

1780 X 120

61

28

MIRL Rwy 10-28 REIL Rws 10 and 28

MIDDLETON, WISCONSIN
Amdt 1B 12AUG21

43°07'N-89°32'W

MIDDLETON MUNI/MOREY FLD (C29)
LOC/DME RWY 10

WAAS CH 62912 W10A	APP CRS 101°	Rwy Idg TDZE Apt Elev	4001 928 928
--	------------------------	-----------------------------	---

RNAV (GPS) RWY 10

MIDDLETON MUNI/MOREY FLD (C29)

RNP APCH.

▼


⚠

Circling NA to Rws 1 and 19. Helicopter visibility reduction below $\frac{3}{4}$ SM NA.

For uncompensated Baro-VNAV systems, LNAV/VNAV NA below -16°C or above 54°C.

MISSED APPROACH: (Do not exceed 185K until APOOZ) Climb to 4000 direct APOOZ then climbing left turn on track 011° to FAVOM then climbing left turn on track 281° to CIKAS and track 270° to NEGUS and hold.

AWOS-3 118.675	MADISON APP CON * 135.45 343.7	UNICOM 123.0 (CTAF) 0
--------------------------	--	---------------------------------



4 NM Holding Pattern		4000	APOOZ	FAVOM	CIKAS	NEGUS
JALOX		CERTO	VGSI and RNAV glidepath not coincident (VGSI Angle 4.00/ TCH 31).			
6000 4000		2800	2800	1.5 NM to RW10	RW10	
GP 3.05° TCH 40		6 NM	4.2 NM	1.5 NM		
CATEGORY	A	B	C	D		
LPV DA	1408-1 $\frac{3}{8}$	480 (500-1 $\frac{3}{8}$)		NA		
LNAV/VNAV DA	1596-1 $\frac{7}{8}$	668 (700-1 $\frac{7}{8}$)		NA		
LNAV MDA	1600-1	672 (700-1)	1600-1 $\frac{7}{8}$ 672 (700-1 $\frac{7}{8}$)	NA		
CIRCLING	1600-1 672 (700-1)	1620-1 692 (700-1)	1640-2 712 (800-2)	NA		

ELEV 928 TDZE 928

MIRL Rwy 10-28 0
REIL Rws 10 and 28 0

VORTAC MSN 108.6 Chan 23	APP CRS 254°	Rwy Idg TDZE Apt Elev	4001 928 928
--	------------------------	-----------------------------	---


VOR RWY 28

MIDDLETON MUNI/MOREY FLD (C29)

T When local altimeter setting not received, use Dane County Rgnl/Truax Fld
A altimeter setting and increase all MDAs 40 feet and S-28 visibility Cat C $\frac{1}{8}$
SM, and Circling visibility Cat C $\frac{1}{4}$ SM. RADAR or DME required. Circling
NA to Rwy 15 and 19. Rwy 28 helicopter visibility reduction below 1 SM NA.
Straight-in Rwy 28 NA at night. Circling Rwy 28 NA at night.

MISSED APPROACH: Climb to 2000 then climbing right turn to 3500 on heading 020° and MSN R-282 to IMMES INT/9.2 DME and hold.

AWOS-3 118.675	MADISON APP CON★ 135.45 343.7	UNICOM 123.0 (CTAF) ①
--------------------------	---	---------------------------------



	A	B	C	D
S-28	1500-1	572 (600-1)	1500-1 ⁵ / ₈ 572 (600-1 ⁵ / ₈)	NA
CIRCLING	1560-1 632 (700-1)	1640-1 712 (800-1)	1660-2 732 (800-2)	NA

FAF to MAP 8.4 NM

Knots	60	90	120	150	180
Min:Sec	8:24	5:36	4:12	3:22	2:48