

|               |         |          |      |
|---------------|---------|----------|------|
| LOC/DME I-HRL | APP CRS | Rwy Idg  | 8301 |
| 111.5         | 356°    | TDZE     | 36   |
| Chan 52       |         | Apt Elev | 36   |

LOC/DME BC RWY 35L  
VALLEY INTL (HRL)

**T** LOC BC unusable from 1NM inbound.  
**A** Disregard glide slope indications.

MISSED APPROACH: Climb to 1600 via I-HRL  
north course to SEBAS/I-HRL 5.5 DME and hold.

|                |                               |                                         |                  |                  |
|----------------|-------------------------------|-----------------------------------------|------------------|------------------|
| ATIS<br>124.85 | VALLEY APP CON<br>120.7 279.5 | HARLINGEN TOWER ★<br>119.3 (CTAF) 317.6 | GND CON<br>121.7 | UNICOM<br>122.95 |
|----------------|-------------------------------|-----------------------------------------|------------------|------------------|

